



AC Tech Settings

P48	04			
P44	25			
P03	02	NP400	NP700	NP1000
P04	03			
P10	04			
P11	04			
P12	04			
P19	5.0			
P20	5.0			
P31 (Run Man)		43.0	38.0	51.0
P33 (Service, Flush, Purge)		15.0	15.0	15.0
P35 (Run Hi)		43.0	38.0	51.0
P36 (Run Lo)		33.0	28.0	38.0

After programming, turn power off then on again.
Motor will start-use down arrow to run speed down to 0.0.

SERVICE (Toggle Down)
RUN AUTO (Center position)
RUN MAN (Toggle Up)

Date	Revision History
06/27/19	Description Add Diode to Aux1 Output

Newport AC Connect
Revision: 06/27/19
Spectra Watermakers
Dwg No WS5 rev 0